
WIRING DIAGRAM

ER 100 I






S1 on (after approx. 50 s) S1 off (overrun time 6 min.) Using a 1-pin switch can cause reverse polarity voltages. Combination with an X2 capacitor necessary!

WIRING DIAGRAM

ER 100 I

Switching option 1





S1 and S2 on (after aprox. 50 s) S1 off (overrun time 6 min.) In addition, the fan can be switched off with switch S2 independent of the room lighting. Using a 1-pin switch can cause reverse polarity voltages. Combination with an X2 capacitor necessary!